



South Hedland Aquatic Centre Redevelopment

- Results from the water samples taken on Monday 6 and Wednesday 8 May show the backwash filters on the main and leisure pools have failed to achieve compliance.
- Results also show that the pre-filter suction line, leading from the balance tank into the filters, had traces of amoeba.
- On Thursday 9 May, Council resolved at the Special Council Meeting for main contractors, CAA, to replace the filter medium in the main and leisure pools.
- The Town has instructed CAA to investigate a potential fault in the pre-filter suction line which may be causing the contamination in the filters.
- Materials for the replacement of the filter medium have been ordered, and are expected to arrive towards the end of the week. Once materials have arrived, work will commence immediately.
- The next water sample will be taken when all remediation works are complete.



Principal Partners



GOVERNMENT OF
WESTERN AUSTRALIA

Department of
Regional Development and Lands



Supporting Partners



GOVERNMENT OF
WESTERN AUSTRALIA

Department of
Sport and Recreation



Australian Government
Department of Regional Australia,
Regional Development and Local Government

